

Fisher Controls International LLC 205 South Center Street P.O. Box 190 Marshalltown, Iowa 50158-0190 USA T (641) 754-2688 F (641) 754-2645

September 13, 2004

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555-0001

To Whom It May Concern:

This is to confirm that this document is publicly available.

Trish Crosser

Assistant to Director of Quality

Fisher Controls Int'l LLC.

Marshalltown IA

FISHER

TEAD

Fisher Controls

FISHER'

Fisher Controls International LLC 205 South Center Street Marshalltown, IA 50158

Fisher Information Notice: FIN 2004-02

June 23, 2004

Subject:

Fisher Pneumatic Instrument Relays with Nitrile Elastomer Diaphragms

Equipment Affected By This Information Notice:

ALL FISHER TYPE 3582 POSITIONERS, TYPE 3583 POSITION TRANSMITTERS, TYPE 3590 POSITIONERS, TYPE 4190 SERIES INDICATING CONTROLLERS, REPLACEMENT TYPE 83L, 83H AND 83U PNEUMATIC RELAYS SOLD TO THE NUCLEAR INDUSTRY THAT UTILIZE NITRILE DIAPHRAGMS.

Purpose:

The purpose of this Fisher Information Notice (FIN) is to alert customers to the possibility of a situation which may affect the customer's application of this equipment whether or not it is a safety-related application of the equipment.

We are informing our customers of record of this circumstance in accordance with Section 21.21 (b) of 10CFR21 because Fisher Controls International LLC is not aware of each and every application or system design and cannot determine whether an anomaly could cause a defect or "failure to comply," relating to a substantial safety hazard.

Receipt of this notice does not necessarily mean that the recipient has been shipped any of the subject equipment. It is expected that the recipients of this notice will review the information for applicability to their facilities, and if required, take the appropriate action as described in the section at the end of this notice.

Applicability:

This notice applies only to the subject equipment supplied by Fisher Controls International LLC that meet any of the following criteria:

- Fisher Type 3582 Positioners with nitrile elastomer diaphragms, shipped since February 1999.
- Fisher Type 3583 Position Transmitters with nitrile elastomer diaphragms, shipped since February 1999.
- Fisher Type 3590 Positioners with nitrile elastomer diaphragms, shipped since February 1999.
- All Fisher Type 4190 Series Indicating Controllers (4194A, B and C Series; 4194HA, HB and HC Series; 4194HS Series; 4194S Series; 4195S Series; 4196A, B, C and S Series) with nitrile elastomer diaphragms, shipped since February 1999.
- All Fisher Types 83L (part of the Type 3582 Positioner and the Type 3583 Position Transmitter), 83H (part of the Type 3590 Positioner), and 83U (part of the Type 4190 Series Indicating Controllers) pneumatic relays with nitrile elastomer diaphragms, shipped as replacement relays for the instruments listed above, since February 1999.

Note: The Type 3582NS nuclear service version Positioners are not affected by this information notice because they do not use nitrile elastomer diaphragms.

For the same reason any high temperature version of any of the instruments listed above is not affected by this notice because the diaphragms in these relays use Fluorelastomer (FKM), polyacrylic (ACM), epichlorohydrin (ECO) materials.

Description of Possible Instrument Relay Problem:

The elastomers used in the diaphragms for the Types 83L, 83H and 83U Relays are designed to provide controlled physical movement, caused by pressure changes acting on the pneumatic relay diaphragms. In order to maintain pressure and still be responsive to small pressure fluctuations, the thickness of the relay diaphragm material is a critical characteristic. If the material is too thick the performance of the relay may be degraded.

Discussion:

In February 1999, Fisher increased the thickness of the nitrile diaphragms in the Type 83 Series relays as part of a material consolidation program

Recently, Fisher was notified that the installed performance of several Type 3582 Positioners did not appear to be acceptable because of reported "sluggish" relay behavior. The most notable characteristic of this behavior is an increase in time required to exhaust the actuator diaphragm case (stroke time).

To correct this problem, Fisher has reduced the thickness of the nitrile diaphragm to its previous, thinner dimensions. Table 1 provides a conversion list for replacement part numbers.

One can determine which type of nitrile diaphragm is present in a given relay by looking at the alignment tabs (See Figure 1) on the diaphragms that extend outside the relay segments:

- The thicker diaphragms are identified by red dots, or red (or pink) wavy lines, or light blue wavy lines.
- The thinner diaphragms are identified by white dots or white wavy lines. This is the same marking used for the pre-1999 diaphragms.

Action Required:

- No action is required for plants that do not have the subject equipment.
- No action is required if the particular relay has not exhibited the behavior described above.
- Use the list of part numbers to determine what inventory is located at the plant site.
- If your plant has experienced problems regarding expected performance from these instruments, or if you discover that you have relays with the thicker diaphragms installed, contact your Fisher Local Business Partner regarding appropriate corrective action.

10CFR21 Implications:

The recipient of this notice is requested to review the information contained in this notice to determine its applicability to his/her facility.

If no equipment meeting the applicability requirements listed above have been provided by Fisher Controls International LLC, then no further action is required.

If equipment meeting the applicability requirements listed above have been supplied and used in a safety-related application, Fisher Controls requests that the recipient of this notice review it and take appropriate action in accordance with 10CFR21.

If there are any questions related to specific valve serial numbers, please contact your local Fisher Controls Representative.

If there are any technical questions or concerns, please contact:

George Baitinger
Manager, Quality Assurance, Marshalltown Operations
Fisher Controls International LLC
205 South Center Street
Marshalltown, IA 50158

Fax: (641) 754-2854




Figure 1. Diaphragm Locating Tabs

Table 1. Replacement Part Numbers

	
Old Part Number	New Part Number
32B0255X022	None*
32B0255X0A2	R3580XRS012
32B0255X0B2	R3580XRS022
32B0255X0D2	None*
32B0255X0F2	32B0255X082
32B0255X0G2	None*
BU9005X0012	None*
BU9005X0022	None*
BU9005X00E2	R3580XRS012
BU9005X00F2	R3580XRS022
BU9005X00K2	None*
R83LX000012	R3580XRS012
R3580XRS012	R3580XRS012
32B0257X0A2	32B0257X0C2
32B0257X0B2	32B0257X0D2
32B0257X0E2	32B0257X0C2
32B0257X0F2	32B0257X0D2
BV5997X0012	None*
BV5997X00A2	32B0257X0C2
BV5997X00B2	32B0257X0D2
CV4084X00A2	None*
CV4084X00B2	None*
CV4084X00C2	None*
32B0315X0A2	None*
R83HX000012	R3590XRS012
	32B0255X022 32B0255X0A2 32B0255X0B2 32B0255X0D2 32B0255X0F2 32B0255X0G2 BU9005X0012 BU9005X0022 BU9005X00F2 BU9005X00F2 BU9005X00K2 R83LX000012 R3580XRS012 32B0257X0A2 32B0257X0B2 32B0257X0B2 32B0257X0F2 BV5997X0012 BV5997X0012 BV5997X00A2 BV5997X00B2 CV4084X00A2 CV4084X00A2 CV4084X00B2 CV4084X00C2 32B0315X0A2

^{*} Part numbers noted as "None" are associated with obsolete product lines and are no longer orderable.